Ship Name: CARUACHI Ship Type: General Dry Cargo Ship

IMO Number: **7716000** Flag: **Venezuela** 

Date Detained: 03/04/2000 Class Society: Det Norske Veritas

Port: Port Everglades, Florida Company(s): Owners, Operators or Managers

Naviera Ulises C.A.

Deficiencies: Code - Category Description

room bilge.

0999 - Other (Safety In General) Engine room presented numerous personnel

safety hazards because of leaking exhaust gas

and improperly maintained electrical

installations.

1540 - Gyro compass Gyro compass was inoperable.

1499 - Other (Prop. & Aux. Improperly maintained stern tube resulted in

Machinery) discharge of oil into U.S. waters.

Ship Name: COLUMBUS PACIFIC Ship Type: Containership

IMO Number: 9122526 Flag: Germany

Date Detained: 03/18/2000 Class Society: Germanischer Lloyd

Port: Seattle, Washington Company(s): Owners, Operators or Managers

Martime-Gesellschaft Fur Maritime

Deficiencies: Code - Category Description

1440 - Bilge pumping General service and ballast pump sea valve

was severely corroded, and leaking through a

temporary repair.

Ship Name: FORTUNA REEFER Ship Type: Refrigerated Cargo Carrier

IMO Number: **7908770** Flag: **Panama** 

Date Detained: 03/02/2000 Class Society: Nippon Kaiji Kyokai

Port: American Samoa Company(s): Owners, Operators or Managers

Rama Shipping Co.

Deficiencies: Code - Category Description

0220 - Certificates of competency STCW Certificates for 3 officers were

restricted to fishing vessels.

0740 - Pumps Emergency fire pump exhaust insulation was

insufficient, and began smoldering during

operation.

0611 - Lifeboat inventory Lifeboat provisions were not stored properly.

1299 - Other (Load Lines) Forward house bulkhead was wasted and

0999 - Other (Safety In General) Main deck catwalk was wasted and unsafe for

crew passage.

Ship Name: FREJA JUTLANDIC Ship Type: Chemical Tankship

IMO Number: 8213548 Flag: Norway

Date Detained: 03/22/2000 Class Society: Det Norske Veritas

Port: Baltimore, Maryland Company(s): Owners, Operators or Managers

**D/S Progress** 

Deficiencies: Code - Category Description

0938 - Hull damage impairing Holed sideshell in the engine room, leaking

seaworthiness excessively through a doubler plate.

1710 - Oil record book Improper entries were made in Oil Record

0610 - Lifeboats Both lifeboats were temporarily repaired with

unsatisfactory soft patches.

1440 - Bilge pumping Engine room bilge pump was inoperative.

1740 - Oil discharge mon/contr Oil discharge monitoring equipment was

system inoperable.

Ship Name: GAZ HORIZON Ship Type: LPG Gas Carrier

IMO Number: 7708687 Flag: Panama

Date Detained: 03/14/2000 Class Society: Lloyd's Register of Shipping

Port: Galveston, Texas Company(s): Owners, Operators or Managers

**Naftomar Shipping and Trading** 

Deficiencies: Code - Category Description

1840 - Instrumentation The fixed gas detection system was inoperable.

0711 - Inert gas system

The inert gas system was inoperable.

2025 - Abandon ship drills

Crew was unable to demonstrate a satisfactory abandon ship drill.

2020 - Fire drills Crew was unable to demonstrate a

satisfactory fire drill.

1099 - Other (alarm - signals) Cargo tank high and low pressure alarms

were inoperable.

1870 - Special requirements Outer door on the electric motor room

air-lock was not self closing, and no visual alarms were installed on the inner or outer

sides of the air-lock.

Ship Name: HUA XIANG Ship Type: Towboat/Tug

IMO Number: 7808267 Flag: Liberia

Date Detained: 03/27/2000 Class Society: China Classification Society

Port: Honolulu, Hawaii Company(s): Owners, Operators or Managers

**China Ocean Engineering Services** 

Deficiencies: Code - Category Description Oily-water separator was inoperable.

1730 - Oily-water separating

equipment

2020 - Fire drills

Crew was unable to demonstrate a

satisfactory fire drill.

0610 - Lifeboats Port lifeboat hull was improperly maintained

and unsafe for use.

Ship Name: **ILHA DO FOGO** Ship Type: General Dry Cargo Ship

IMO Number: 6915611 Flag: Panama

Date Detained: 03/30/2000 Class Society: Panama Shipping Register

Port: Fall River, Massachusets Company(s): Owners, Operators or Managers

**Global Shipping Lines** 

Deficiencies: Code - Category Description

1730 - Oily-water separating Vessel is equipped with a 100 ppm oily-water

equipment separator; required to have 15 ppm device

before July 1998.

Ship Name: **INAGUA SPRAY** Ship Type: Ro-Ro-Cargo Ship

IMO Number: 6703989 Flag: Panama

Date Detained: 03/30/2000 Class Society: Not Classed

> Port: Miami, Florida Company(s): Owners, Operators or Managers

> > Caicos Maritime Inc.

Deficiencies: Code - Category Description

Oily-water separator was improperly 1730 - Oily-water separating

equipment maintained and malfunctioning. Ship Name: **INFINITY PEARL** Ship Type: Ro-Ro-Cargo Ship

IMO Number: 7811434 Flag: Saint Vincent and the Grenadines

Date Detained: 03/29/2000 Class Society: Det Norske Veritas

Company(s): Owners, Operators or Managers Port: Tampa, Florida

Wichita Falls Group, Ltd.

Deficiencies: Code - Category Description

0113 - Cargo ship safety radio Cargo Ship Safety Radio Certificate was 2020 - Fire drills

Crew was unable to perform a satisfactory

fire drill.

Crew was unable to perform a satisfactory 2025 - Abandon ship drills

abandon ship drill.

0740 - Pumps Fire pumps were unable to produce sufficient

water pressure.

0611 - Lifeboat inventory Lifeboat inventories were insufficient.

Ship Name: KLAAS I Ship Type: General Dry Cargo Ship

Flag: Honduras IMO Number: 7104427

Date Detained: 03/09/2000 Class Society: Honduras International Naval

**Surveying and Inspection Bureau** 

Port: Miami, Florida Company(s): Owners, Operators or Managers

Merchandise Shipping & Trading Co.

Inc.

Deficiencies: Code - Category Description

> 1730 - Oily-water separating Oily-water separator was inoperable.

equipment

1705 - SOPEP missing or deficient **Shipboard Oil Pollution Emergency Plan** 

(SOPEP) was not updated.

0699 - Other (Life Saving Vessel not in compliance with numerous, Flag

State requirements, including firemen's Appliances)

outfits, fire control plans, international shore connection, fire hoses, rescue boat and launching appliance, lifejackets and

emergency instructions.

1620 - Main installation GMDSS equipment was inoperable.

1270 - Doors Port side watertight door could not be made

watertight.

Ship Name: MAERSK BRIDGETOWN Ship Type: General Dry Cargo Ship

IMO Number: 9137820 Flag: Cyprus

Date Detained: 03/07/2000 Class Society: Det Norske Veritas

Company(s): Owners, Operators or Managers Port: San Juan, Puerto Rico

**Cargrove Shipping Limited** 

Deficiencies: Code - Category Description

> 0615 - Rescue boats The rescue boat pontoon was holed, and the

crew had not performed regular, rescue boat

launching and training.

Ship Name: MANDARIN MOON Ship Type: Bulk Carrier

IMO Number: 8309359 Flag: **Singapore** 

Date Detained: 03/18/2000 Class Society: China Classification Society

Port: Long Beach, California Company(s): Owners, Operators or Managers

**Dasin Shipping Pte LTD** 

Deficiencies: Code - Category Description

> 2025 - Abandon ship drills The vessel's crew could not perform a

> > satisfactory abandon ship drill.

0720 - Fire fighting equipment Fire main piping was improperly maintained,

causing oil contamination.

Ship Name: MITSA Ship Type: Bulk Carrier

IMO Number: 7326764 Flag: Malta

Date Detained: 03/31/2000 Class Society: Lloyd's Register of Shipping

Port: Hampton Roads, Virginia Company(s): Owners, Operators or Managers

> Euro Carriers, S.A. Force Shipping Ltd.

Deficiencies: Code - Category Description

> 2530 - Resources and Personnel Vessel's crew could not produce

> > documentation to verify officers received shipboard familiarization training, nor were they fully conversant with the Company's SMS.

Officers and crew not familiar with 2545 - Reports/analysis of

non-conformities, etc. procedures for reporting non-conformities,

and no non-conformity reports have been filed

2525 - Masters responsibility and The Safety Management System was not

authority

effectively implemented.

2550 - Maintenance of ship and Critical equipment, which if failed could

equipment result in a hazardous situation, had not been

identified in the Safety Management System.

Ship Name: PU PROGRESS Ship Type: Containership

IMO Number: 7726914 Flag: Singapore

Date Detained: 03/01/2000 Class Society: Germanischer Lloyd

Company(s): Owners, Operators or Managers Port: New Orleans, Louisiana

P.U. Progress Pte., Ltd.

Deficiencies: Code - Category Description

0740 - Pumps One main fire pump was inoperable.

0699 - Other (Life Saving Starboard lifeboat and davit was not properly

Appliances) maintained; fuel tank not suitable for service,

and davit sheaves were seized.

Starboard main diesel engine was not properly 1410 - Propulsion main engine

maintained, nor functioning properly.

Ship Name: **RED CEDAR** Ship Type: **Bulk Carrier** 

IMO Number: 9145059 Flag: Malta

Date Detained: 03/25/2000 Class Society: Registro Italiano Navale

Port: Long Beach, California Company(s): Owners, Operators or Managers

Cedar Shipping Co. LTD.

Deficiencies: Code - Category Description

2020 - Fire drills Crew could not perform a satisfactory fire

2025 - Abandon ship drills Crew failed abandon ship drill.

Ship Name: SEA SAPPHIRE Ship Type: Bulk Carrier

IMO Number: 9157349 Flag: Panama

Date Detained: 03/16/2000 Class Society: Nippon Kaiji Kyokai

Port: Long Beach, California Company(s): Owners, Operators or Managers

Paraiso Shipping

Deficiencies: <u>Code - Category</u> <u>Description</u>

2020 - Fire drills Crew could not perform a satisfactory fire

0740 - Pumps Emergency fire pump did not supply adequate

water pressure.

0999 - Other (Safety In General) Vessel's paint locker door was missing.

Ship Name: SHUNKOH Ship Type: Refrigerated Cargo Carrier

IMO Number: 8518819 Flag: Singapore

Date Detained: 03/20/2000 Class Society: Nippon Kaiji Kyokai

Port: American Samoa Company(s): Owners, Operators or Managers

Shunko Shipping Corporation

Deficiencies: <u>Code - Category</u> <u>Description</u>

0220 - Certificates of competency Crew members did not have STCW

2020 - Fire drills Crew failed the fire drill.

2025 - Abandon ship drills Crew failed the abandon ship drill.

0610 - Lifeboats Port lifeboat was improperly maintained and

not ready for immediate use.

Ship Name: STAR DRIVANGER Ship Type: General Dry Cargo Ship

IMO Number: **7620603** Flag: **Singapore** 

Date Detained: 03/22/2000 Class Society: Det Norske Veritas

Port: Long Beach, California Company(s): Owners, Operators or Managers

**Masterbulk Private Limited** 

Deficiencies: <u>Code - Category</u> <u>Description</u>

satisfactory abandon ship drill.

satisfactory fire drill.

Ship Name: TAMA HOPE Ship Type: Refrigerated Cargo Carrier

IMO Number: 8517346 Flag: Bahamas

Date Detained: 03/31/2000 Class Society: Nippon Kaiji Kyokai

Port: Seattle, Washington Company(s): Owners, Operators or Managers

Tama Hope Shipping Co. Ltd.

Deficiencies: Code - Category Description

0899 - Other (accid. prevent.) Fire screen doors in stair tower and machinery

space emergency escape trunk were

1420 - Cleanliness of engine room

An excessive amount of oil was in the

machinery space bilge.

Ship Name: TOKYO BAY Ship Type: Refrigerated Cargo Carrier

IMO Number: 7714521 Flag: Malta

Date Detained: 03/14/2000 Class Society: Det Norske Veritas

Port: Cape Canaveral, Florida Company(s): Owners, Operators or Managers

Tokyo Bay Shipping Co, Ltd

Deficiencies: Code - Category Description

0630 - Launch arrangt. for Port lifeboat could not be launched because of

survival craft a seized brake drum.

0610 - Lifeboats Starboard lifeboat propulsion was

inoperable; engine disassembled.